




Existing Conditions: View from Upper Thumb Picnic Area looking down Peña Blanca Canyon towards Castle Rock.

**Visual Simulation 1:  
Western Corridor from Upper  
Thumb Picnic Area at Peña  
Blanca Lake Recreation Area.**

An example, partially-blocked view  
of the Western Corridor from a  
Concern Level 1 travelway.

**Direction:** Southwest

**Distance to Nearest Pole:** 1.2 mi



Visual Simulation: Depicting self-weathering monopoles.

